

A.	B.	C.	D.	E.	F.	G.	H.	I.	J.	K.	L.	M.	N.	O.	P.	Q.	R.	S.	T.	U.	V.
1. Case Name	Hess Corporation Framework Project Restoring Confidence (HFC-HR)																				
2. P#	001-148																				
3. APPENDIX	APPENDIX - Data entry and status into system that 1 call is a block defective & can disrupt Holden acquisitions																				
4. Case Inventory Document Version 1.3 4057514	Case Inventory Document Version 1.3 4057514																				
5. AOC ID	6. AOC Type	7. AOC Details	8. Contaminated Contamination	9. AOC Status	10. Status Date	11. Incident #	12. DEP AOC Number	13. Contaminated Media	14. Contaminants of Concern	15. Assessment Concern	16. Appropriate Remediation Standards	17. Exposure Route	18. Additional Exposure Route	19. Risk Type	20. Additional Risk Type	21. Risk Type	22. Additional Risk Type	23. Activity			
53. AOC-37	Storage tank and appurtenance - Loading and unloading tanks	No. 2 Oil Detergent and Adhesive Truck Unloading Area	Undetermined	PA	10/06/2015			Mixed Media	VO + BN		Harmful								Surveyed surface, debris, sandy concrete slabs, and one approximately 3x4-Sigma unlined stainless steel tank were observed. The stainless steel tank was identified as part of the No. 2 Oil Detergent and Adhesive Truck Unloading Area. Poured water with a red color was observed after a concrete secondary containment area. Several areas of staining, erosion, and/or sedimentation were observed near the bottom of the concrete secondary containment area. Further investigation is planned.		
54. AOC-38	Storage and staging area - Storage pad and pens	No.3 Truck Unloading Pesticides/Chemicals Area	Undetermined	PA	10/06/2015			Soil	Mixed		Remediation Standards	Groundwater/Drainage							Soil investigation at the No. 3 Truck Unloading Area indicated no contamination concentrations are above applicable NDEP standards. Further investigation is planned.		
55. AOC-39	Storage tank and appurtenance - Loading and unloading tanks	EADC Truck Unloading Area	Undetermined	PA	10/06/2015			Mixed Media	VO + BN		Remediation Standards								One remediation activity was conducted in the east portion of section "B" storage tanks, which were large USTs situated on concrete supports. Several piping carts and support structures were observed in the area. The tanks were heavily stained. The staining was described as the EADC Truck Unloading Area. Based on observations, no further investigation is planned.		
56. AOC-40	Storage tank and appurtenance - Loading and unloading tanks	Fresh Asphalt Unloading Area	Undetermined	PA	10/06/2015			Mixed Media	Other		Remediation Standards								No further investigation at the Fresh Asphalt Unloading Area is planned. A soil investigation is planned in the vicinity of the Fresh Asphalt Unloading Area. Based on observations, no further investigation is planned.		
57. AOC-41	Storage tank and appurtenance - Loading and unloading tanks	Gasoline Adhesive Truck Unloading Area	Undetermined	PA	10/06/2015			Mixed Media	VO		Remediation Standards								No staining or evidence of release of materials.		
58. AOC-42	Storage tank and appurtenance - Loading and unloading tanks	Monomer Truck Unloading Area/Decorativeization Area	Yes	PASI	10/06/2015			Circulated Water	VO		Remediation Standards	Groundwater							Soil investigation at the No. 1 Truck Unloading Area indicated no contamination concentrations are above applicable NDEP standards. Further investigation is planned.		
59. AOC-43	Storage tank and appurtenance - Loading and unloading tanks	Truck Unloading (Power Truck) Area 1	Undetermined	PA	10/06/2015			Soil	VO + BN		Remediation Standards	Groundwater/Drainage							Groundwater samples collected to investigate the Ground Landfill (NOCC-2) indicate the presence of VOCs in the vicinity of the pumps and piping at the NOCC. No further investigation is planned in the area as there is ongoing groundwater monitoring contractor is planned.		
60. AOC-44	Storage tank and appurtenance - Loading and unloading tanks	Truck Unloading (Power Truck) Area 2	Undetermined	PA	10/06/2015			Mixed Media	VO + BN		Remediation Standards	Groundwater							Soil investigation at the No. 2 Truck Unloading Area indicated no contamination concentrations are above applicable NDEP standards. Further investigation is planned.		
61. AOC-45	Storage tank and appurtenance - Loading and unloading tanks	SSU Truck Unloading Area	Undetermined	PA	10/06/2015			Soil	BN		Remediation Standards	Groundwater/Drainage							Soil investigation conducted at the Fresh Asphalt Unloading Area indicated no VOCs or NDEP standards. Further investigation is planned.		
62. AOC-46	Storage tank and appurtenance - Loading and unloading tanks	Stop Gasoline Unloading Area	Undetermined	PA	10/06/2015			Mixed Media	VO + BN		Remediation Standards	Groundwater							Soil investigation at the Stop Gasoline Unloading Area indicated no VOCs or NDEP standards. Further investigation is planned.		
63. AOC-47	Storage tank and appurtenance - Loading and unloading tanks	Blowout Truck Unloading Area	Undetermined	PA	10/06/2015			Soil	Mixed		Remediation Standards	Groundwater/Drainage							Soil investigation at the Blowout Truck Unloading Area indicated no VOCs or NDEP standards. Further investigation is planned.		
64. AOC-48	Storage tank and appurtenance - Pump, above/below ground	Gasoline Dispenser and AST	Undetermined	PA	10/06/2015			Mixed Media	VO		Remediation Standards	Groundwater							Soil investigation at the Gasoline Dispenser and AST indicated no VOCs or NDEP standards. Further investigation is planned.		
65. AOC-49	Storage tank and appurtenance - Above ground storage tank	Electrical Step Down/No. 2 Fuel Oil AST's	Undetermined	PA	10/06/2015			Soil	Mixed		Remediation Standards	Groundwater							The two ASTs were found at a concrete block wall where the ASTs were connected to two metal tanks. No staining or evidence of releases was observed during the review of the tanks. No further investigation is planned.		
66. AOC-50	Storage tank and appurtenance - Above ground storage tank	Refinery Warehouses Diesel/No. 2 Fuel Oil AST's	Undetermined	PA	10/06/2015			Mixed Media	BN		Remediation Standards	Groundwater							Soil investigation conducted near the two fuel oil tanks indicated no VOCs or NDEP standards. Further investigation is planned.		
67. AOC-51	Storage tank and appurtenance - Above ground storage tank	2nd Reserve Boiler AST	Undetermined	PA	10/06/2015			Mixed Media	BN		Remediation Standards	Groundwater							The two fuel oil tanks were connected to two metal tanks. No staining or evidence of releases was observed during the review of the tanks. No further investigation is planned.		
68. AOC-52	Storage tank and appurtenance - Above ground storage tank	TK-7825 AST	Undetermined																Soil investigation at the TK-7825 AST indicated no VOCs or NDEP standards. No further investigation is planned.		
69. AOC-53	Storage tank and appurtenance - Above ground storage tank	TK-200-1000 gallons - Waste/Hazardous Chemicals	Undetermined	PA	10/06/2015			Mixed Media	BN + Mixed		Remediation Standards	Groundwater							Soil investigation conducted near the TK-200-1000 gallon tank indicated no VOCs or NDEP standards. Further investigation is planned.		
70. AOC-54	Storage tank and appurtenance - Above ground storage tank	TK-200-1000 gallons - Waste/Hazardous Chemicals	Undetermined	PA	10/06/2015			Mixed Media	VO		Remediation Standards								Based on site observations at the TK-200-1000 gallon tank, a potential exists for release of hazardous substances. Further investigation is planned.		

A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T <u></u>
Case Name: Hess Corporation Farmer Piping Company Inc-CPN																			
P#:																			
008148																			
Case Inventory Document Version 1.3 10/25/14																			
ADC ID	ADC Type	ADC Details	Confirmed Contamination	ADC Status	Incident Date	Incident #	DE/ADC Number	Contaminated Media	Contaminants of Concern	Additional Contaminants of Concern	Activity								
1	ADC-45	Storage tank and appurtenance - Above ground storage tank	Unetermined	PA	10/26/2013			Soil	VO + BN	Metals	Remediation Standards	Groundwater	Groundwater	Groundwater	Groundwater	Groundwater	Groundwater	Groundwater	Soil investigations conducted near the Fourth Tankfield Area indicate that no further investigation is appropriate NUEP standards. Further investigation is planned.
2	ADC-56	Storage tank and appurtenance - Above ground storage tank	Unetermined	PA	10/26/2013			Metals/Metals	VO + BN	Metals	Remediation Standards	Ground Water	Ground Water	Soil investigations conducted near the Second Reservoir Tankfield Area indicate that no further investigation is appropriate NUEP standards. Further investigation is planned.					
3	ADC-57	Storage tank and appurtenance - Above ground storage tank	Unetermined	PA	10/26/2013			Metals/Metals	VO + BN	Metals	Remediation Standards	Ground Water	Ground Water	Soil investigations conducted near the Second Reservoir Tankfield Area indicate that no further investigation is appropriate NUEP standards. Further investigation is planned.					
4	ADC-58	Storage tank and appurtenance - Above ground storage tank	Unetermined	PA	10/26/2013			Metals/Metals	VO	Metals	Remediation Standards	Ground Water	Ground Water	Soil investigations conducted near the Chemical Storage Tankfield Area indicate that no further investigation is appropriate NUEP standards. Further investigation is planned.					
5	ADC-59	Storage tank and appurtenance - Above ground storage tank	Unetermined	PA	10/26/2013			Metals/Metals	VO	Metals	Remediation Standards	Ground Water	Ground Water	Soil investigations conducted near the Chemical Storage Tankfield Area indicate that no further investigation is appropriate NUEP standards. Further investigation is planned.					
6	ADC-60	Storage tank and appurtenance - Above ground storage tank	Unetermined	PA	10/26/2013			Metals/Metals	VO + BN	Metals	Remediation Standards	Ground Water	Ground Water	Soil investigations conducted near the Chemical Storage Tankfield Area indicate that no further investigation is appropriate NUEP standards. Further investigation is planned.					
7	ADC-61	Other areas of concern - Other discharge area	Unetermined	PA	10/26/2013			Metals/PnHs	PCBs	PCBs	Remediation Standards	Ground Water	Ground Water	Soil investigations conducted near the Chemical Storage Tankfield Area indicate that no further investigation is appropriate NUEP standards. Further investigation is planned.					
8	ADC-62	Other areas of concern - Other discharge area	Unetermined	PA	10/26/2013			Metals/PnHs	PCBs	PCBs	Remediation Standards	Ground Water	Ground Water	Soil investigations conducted near the Chemical Storage Tankfield Area indicate that no further investigation is appropriate NUEP standards. Further investigation is planned.					
9	ADC-63	Other areas of concern - Other discharge area	Unetermined	PA	10/26/2013			Metals/PnHs	PCBs	PCBs	Remediation Standards	Ground Water	Ground Water	Soil investigations conducted near the Chemical Storage Tankfield Area indicate that no further investigation is appropriate NUEP standards. Further investigation is planned.					
10	ADC-65	Other areas of concern - Other discharge area	Unetermined	PA	10/26/2013			VO+Metals			Remediation Standards	Ground Water	Ground Water	Soil investigations conducted near the Chemical Storage Tankfield Area indicate that no further investigation is appropriate NUEP standards. Further investigation is planned.					
11	ADC-66	Other areas of concern - Other discharge area	Unetermined	No Sampling Trigger	10/26/2013			VO + BN			Remediation Standards	Ground Water	Ground Water	The active rail spur was observed between the current PnHs sampling location and the former RR spur. No further investigation is planned.					
12	ADC-64	Other areas of concern - Other discharge area	Unetermined	No Sampling Trigger	10/26/2013			VO+Metals			Remediation Standards	Ground Water	Ground Water	The active rail spur was observed between the current PnHs sampling location and the former RR spur. No further investigation is planned.					
13	ADC-65	Other areas of concern - Other discharge area	Unetermined	No Sampling Trigger	10/26/2013			VO+Metals			Remediation Standards	Ground Water	Ground Water	The active rail spur was observed between the current PnHs sampling location and the former RR spur. No further investigation is planned.					
14	ADC-66	Other areas of concern - Other discharge area	Unetermined	No Sampling Trigger	10/26/2013			VO+Metals			Remediation Standards	Ground Water	Ground Water	The active rail spur was observed between the current PnHs sampling location and the former RR spur. No further investigation is planned.					
15	ADC-67	Other areas of concern - Underground piping including industrial process water	Unetermined	No Sampling Trigger	10/26/2013			VO+Metals			Remediation Standards	Ground Water	Ground Water	Soil investigations conducted near the Fourth Tankfield Area indicate that no further investigation is appropriate NUEP standards. Further investigation is planned.					
16	ADC-68	Other areas of concern - Underground piping including industrial process water	Unetermined	No Sampling Trigger	10/26/2013			VO+Metals			Remediation Standards	Ground Water	Ground Water	Soil investigations conducted near the Fourth Tankfield Area indicate that no further investigation is appropriate NUEP standards. Further investigation is planned.					
17	ADC-69	Other areas of concern - Underground piping including industrial process water	Unetermined	No Sampling Trigger	10/26/2013			VO+Metals			Remediation Standards	Ground Water	Ground Water	Soil investigations conducted near the Fourth Tankfield Area indicate that no further investigation is appropriate NUEP standards. Further investigation is planned.					

A.	B.	C.	D.	E.	F.	G.	H.	I.	J.	K.	L.	M.	N.	O.	P.	Q.	R.	S.	T.	U.	V.
1. Case Name Hess Concentration Frame/Poly Resting Countries (HCR-P)																					
2. P# #00148																					
3. APPLICANT: Do not copy and paste into more than 1 cell in a row - due to character limit																					
4. Case Inventory Document Version 1.3 4/05/2014																					
5. AOC ID	AOC Type	AOC Details	Confined Contamination	AOC Status	Incident #	IEER/AOC Number	Contaminated Media	Contaminants of Concern	Action(s) Taken	Appropriate Remediation Standards	Exposure Route	Additional Exposure Route	RA Type	Additional RA Type	RA Type	Additional RA Type	RA Type	Additional RA Type	RA Type	Activity	
56. AOC-C70	Other areas of concern - Underground piping including industrial process sewer	Specie (Former Texas Eastern) Pipeline 10" diameter line	Undetermined	No Sampling Trigger	10/05/2015		Soil	VO + BM		Remediation Standards										Portions of a pipeline were observed extending from the facility west through the property. The pipeline is owned by Specie Energy and is used to transport natural gas and surface products as well as oil. The pipeline leads to a portion of the Facility that is located to the west of the MTEC Unit. No storage tanks or structures exist observed along the site walls. No further investigation is planned.	
57. AOC-C71	Other areas of concern - Underground piping including industrial process sewer	Specie (Former Texas Eastern) Pipeline 12" line	Undetermined	No Sampling Trigger	10/05/2015		Soil	VO + BM		Remediation Standards										Portion of the facility extends through the property. The pipeline is owned by Specie Energy and is used to transport natural gas and surface products as well as oil. The pipeline leads to a portion of the Facility that is located to the west of the MTEC Unit. No storage tanks or structures exist observed along the site walls. No further investigation is planned.	
58. AOC-C72	Other areas of concern - Underground piping including industrial process sewer	Central Piping (stainless)	Undetermined	No Sampling Trigger	10/05/2015		Soil	VO + BM		Remediation Standards										A portion of the facility extends through the property. The pipeline is owned by Specie Energy and is used to transport natural gas and surface products as well as oil. The pipeline leads to a portion of the Facility that is located to the west of the MTEC Unit. No storage tanks or structures exist observed along the site walls. No further investigation is planned.	
59. AOC-C73	Other areas of concern - Other discharge area	TEL Building (None)	Undetermined	PA	10/05/2015		Soil	VO+ Metals		Remediation Standards										Soil investigations conducted near the Terminal Lead (TEL) Building building indicate no contamination is reported above NDEP standards. No further investigation is planned.	
60. AOC-C74	Other areas of concern - Other discharge area	TEL Building (Soil)	Undetermined	PA	10/05/2015		Soil	VO+ Metals		Remediation Standards										Soil investigations conducted near the Terminal Lead (TEL) Building building indicate no contamination is reported above NDEP standards. No further investigation is planned.	
61. AOC-C75	Other areas of concern - Other discharge area	Former Canning Plant AST	Undetermined	PA	10/05/2015		Soil	VO + BM		Remediation Standards										Soil investigations conducted near the former Canning plant indicates no contamination is reported above NDEP standards. Further investigation is planned.	
62. AOC-C76	Storage tank and appurtenance - Above ground storage tank	Former Canning Plant Loading Area	Undetermined	PA	10/05/2015		Soil	VO + BM		Remediation Standards										Based on the historical use of the former plant, a potential release may occur if storage tanks are breached. Further investigation is planned.	
63. AOC-C77	Storage tank and appurtenance - Above ground storage tank	Former Petroleum Solvents AST	Undetermined	PA	10/05/2015		Soil	VO		Remediation Standards										Soil investigations conducted near the tank indicate no above applicable NDEP standards. Further investigation is planned.	
64. AOC-C78	Drainage system and sewer - Surface water body	Administrative Building Drainage Channel	Undetermined	PA	10/05/2015		Soil	VO		Remediation Standards										Based on the historical use of the former plant, a potential release may occur if drainage channels are breached. Further investigation is planned.	
65. AOC-C79	Drainage system and sewer -Drainage waste and slurry	Former Drainage System/Pudding	Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former plant indicate no above applicable NDEP standards.	
66. AOC-C80	Other areas of concern - Other discharge area	Former Coker Topping Unit	Undetermined	PA	10/05/2015		Soil	VO + BM	Metals	Remediation Standards										Soil investigations conducted near the former plant indicate no above applicable NDEP standards. Further investigation is planned.	
67. AOC-C81	Discharge and disposal area - Incinerator	Former Marine Terminal Building	Undetermined	No Sampling Trigger	10/05/2015		Soil	VO		Remediation Standards										Based on the history of the facility made by the former marine terminal, there may be some residual contaminants, core samples are one way of the detection. No further investigation is planned.	
68. AOC-C82	Other areas of concern - Other discharge area	Historic Farm Towns	Undetermined	No Sampling Trigger	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former town indicate no above applicable NDEP standards.	
69. AOC-C83	Storage tank and appurtenance - Above ground storage tank	Former Tank N. of Admin Building	Undetermined	PA	10/05/2015		Soil	Metals		Remediation Standards										Soil investigations conducted near the former tank indicate no above applicable NDEP standards.	
70. AOC-C84	Storage tank and appurtenance - Above ground storage tank	Name (BLK/TK/ETD & TIC/ABD)	Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former tank indicate no above applicable NDEP standards.	
71. AOC-C85	Storage tank and appurtenance - Above ground storage tank	Truck Rack (TRL)	Undetermined	PA	10/05/2015		Soil	VO + BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
72. AOC-C86	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	Metals		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
73. AOC-C87	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
74. AOC-C88	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
75. AOC-C89	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
76. AOC-C90	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO + BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
77. AOC-C91	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	Metals		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
78. AOC-C92	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
79. AOC-C93	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
80. AOC-C94	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
81. AOC-C95	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO + BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
82. AOC-C96	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	Metals		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
83. AOC-C97	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
84. AOC-C98	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
85. AOC-C99	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
86. AOC-C100	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO + BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
87. AOC-C101	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	Metals		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
88. AOC-C102	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
89. AOC-C103	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
90. AOC-C104	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
91. AOC-C105	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO + BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
92. AOC-C106	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	Metals		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
93. AOC-C107	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
94. AOC-C108	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
95. AOC-C109	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
96. AOC-C110	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO + BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
97. AOC-C111	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	Metals		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
98. AOC-C112	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
99. AOC-C113	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
100. AOC-C114	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
101. AOC-C115	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO + BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
102. AOC-C116	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	Metals		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
103. AOC-C117	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
104. AOC-C118	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
105. AOC-C119	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
106. AOC-C120	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO + BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
107. AOC-C121	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	Metals		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
108. AOC-C122	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
109. AOC-C123	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
110. AOC-C124	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
111. AOC-C125	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO + BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
112. AOC-C126	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	Metals		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
113. AOC-C127	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
114. AOC-C128	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
115. AOC-C129	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
116. AOC-C130	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	VO + BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
117. AOC-C131	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	Metals		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
118. AOC-C132	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015		Soil	BM		Remediation Standards										Soil investigations conducted near the former truck rack indicate no above applicable NDEP standards.	
119. AOC-C133	Storage tank and appurtenance - Above ground storage tank		Undetermined	PA	10/05/2015																

A.	B.	C.	D.	E.	F.	G.	H.	I.	J.	K.	L.	M.	N.	O.	P.	Q.	R.	S.	T.	U.	V.
1. Case Name: Hess Concentration Frame/Poly Resting Countries (HCR-PF)																					
2. P# #00148																					
3. APPENDANT: Due care and cause to ensure that 1 and all other documents & case direct/hold relevant information																					
4. Case Inventory Document Version 1.3 4657914																					
AOC ID	AOC Type	AOC Details	Contaminated Construction	AOC Status	Start Date	Incident #	IEC AOC Number	Contaminated Media	Concern	Assessment	Concern	Concern	Appropriate Response	Emergency Response	Additional Response	RA Type	Additional RA Type	RA Type	Additional RA Type	Activity	
5	Other areas of concern - Other discharge area	Plain Kicks Out Drain	Unetermined	PA	10/05/2015			Soil	Metals				Remediation Standards	Hazardous/Chemical							
103 AOC-057	Other areas of concern - Other discharge area	Compressor Building	Unetermined	PA	10/05/2015			Soil	VO + BN	Metals	EPH		Remediation Standards	Hazardous/Chemical							
104 AOC-058	Other areas of concern - Discharged area or spill area	Crushing Tower	Unetermined	PA	10/05/2015			Soil	VO + BN	Metals			Remediation Standards	Hazardous/Chemical							
105 AOC-059	Other areas of concern - Discharged area or spill area	Drum Compound (OC-Lot)	Unetermined	PA	10/05/2015			Soil	Metals				Remediation Standards	Hazardous/Chemical							
106 AOC-060	Storage and staging area - Storage pad and area	North Deck - Yard	Unetermined	No Sampling T-Page*	10/05/2015			Soil	BN + Metals				Remediation Standards								
107 AOC-061	Storage and staging area - Storage pad and area	TK-701A and TK-701B	Unetermined	No Sampling T-Page*	10/05/2015			Soil	Other				Remediation Standards								
108 AOC-062	Storage tank and equipment - Above ground storage tank	Waste Water Treatment - Tank #1	Yrs	PA	10/05/2015			Soil	VO + BN				Remediation Standards								
109 AOC-063	Storage tank and equipment - Above ground storage tank	Waste Water Treatment-TK-1010	Yrs	PA	10/05/2015			Soil	BN				Remediation Standards								
110 AOC-064	Storage and staging area - Storage pad and area	Waste Water Treatment Storage Area	Yrs	PA	10/05/2015			Ground Water	VO				Remediation Standards								
111 AOC-065	Other areas of concern - Other discharge area	Baker Area	Unetermined	PA	10/05/2015			Soil	Metals				Remediation Standards	Hazardous/Chemical							
112 AOC-066	Storage tank and equipment - Above ground storage tank	Above Ground Pump Room			10/05/2015			Soil	VO + BN				Remediation Standards								
113 AOC-067	Discharge water and waste - Storm water diversion pond and free pond	Storm & Process Sewers -			10/05/2015			Soil	VO + BN				Remediation Standards								
114 AOC-068	Other areas of concern - Hazardous substance storage or handling area	Chemical Storage Adjacent to Cooling Water Tower			10/05/2015			Ground Water	VO+Metals				Remediation Standards	Ground Water							
115 AOC-069	Storage and staging area - Storage pad and area	Layout Yard	Unetermined	No Sampling T-Page*	10/05/2015			Soil	BN + Metals	PCBs			Remediation Standards	Hazardous/Chemical							
116 AOC-070	Other areas of concern - Other discharge area	Crating Plant	Unetermined	PA	10/05/2015			Min/Metals	VO + BN				Remediation Standards								
117 AOC-071	Other areas of concern - Other discharge area	Varient Land (Sod)	Unetermined	PA	10/05/2015			Soil	BN + Metals				Remediation Standards	Hazardous/Chemical							
118 AOC-072	Other areas of concern - Other discharge area	Fire Pipe/Pipe Areas	Unetermined	PA	10/05/2015			Min/Metals	VO + BN				Remediation Standards								
119 AOC-073	Drainage system and area - Surface water body	North Orange Drin	Unetermined	PA	10/05/2015			Min/Metals	VO + BN				Remediation Standards								
120 AOC-074	Other areas of concern - Other discharge area	North/South Docks	Unetermined	No Sampling T-Page*	10/05/2015			Soil	VO + BN				Remediation Standards								
121 AOC-075	Other areas of concern - Other discharge area	Abandoned Filling	Unetermined	No Sampling T-Page*	10/05/2015			Soil	Metals				Remediation Standards								
122 AOC-076	Storage and staging area - Storage pad and area	Drum Storage Compound	Unetermined	PA	10/05/2015			Soil	Metals				Remediation Standards	Hazardous/Chemical							
123 AOC-077	Other areas of concern - Other discharge area	NB Terminal Building	Unetermined	No Sampling T-Page*	10/05/2015			Soil	PAHs				Remediation Standards								
124 AOC-078	Other areas of concern - Other discharge area																				

A.	B.	C.	D.	E.	F.	G.	H.	I.	J.	K.	L.	M.	N.	O.	P.	Q.	R.	S.	T.	U.	V.
1. Case Name	Hess Concentration Frame Pump Resting Condition (HCFPR)	2. P#	00148	3. AOC#	ANOC-147: Due to case and costs to move this 1 case at a time due to E case direct hold acquisition	4. Case Inventory Document Version 1.3	REC-57514														
AOC ID	AOC Type	AOC Details	Confirmed Contamination	AOC Status	Start Date	Incident #	REC AOC Number	Contaminated Concern	Concern of Concern	Action Taken	Appropriate Response Standard	Emergency Route	Additional Response Route	Additional RA Type	Additional RA Type	WHS or Other Magnitude of Evaluation Conducted?	Activity				
1251	AOC-109	Drainage system and area - Dry soil and sand	Truck Rock Sump	Unetermined	PA	10/02/2015		Household Media	VO + BN		Remediation Standards						Based on the site observations of a sump located in the Truck Rock Sump. A visual code for a visual of the site was developed. Further investigation will be conducted to determine if the site is in compliance with applicable standards. Further investigation is planned.				
1261	AOC-110	Other areas of concern - Other discharge area	Dry Yorkfield Offshore Separator	Unetermined	PA	10/02/2015		Household Media	VO + BN		Remediation Standards						Based on the site observations and the dry organic residue observed in the separator. Further investigation will be conducted to determine if the site is in compliance with applicable standards. Further investigation is planned.				
1271	AOC-111	Storage and staging area - Storage pad and area	Chemical Storage Area	Unetermined	PA	10/02/2015		Household Media	VO + BN		Remediation Standards						Based on the visual portion of the Johnson System D site review. Further investigation is planned.				
1281	AOC-112	Other areas of concern - Underground piping including industrial process sewer	Unknown / Piping Along Avenue B	Unetermined	No Sampling Trigger	10/02/2015		Household Media	VO + BN		Remediation Standards						Based on the site review of the piping including industrial process sewer for the Johnson System D site review. Further investigation is planned.				
1291	AOC-113	Other areas of concern - Other discharge area	2nd Review Tankless Oil/Water Separator	Unetermined	PA	10/02/2015		Household Media	VO + BN		Remediation Standards						No starting or evidence of release was observed in the vicinity of the drums, tanks, and gauges. Based on the site observations, no further investigation is planned at this time.				
1301	AOC-114	Storage and staging area - Storage pad and area	Waste Water Treatment - Above Area	Unetermined	No Sampling Trigger	10/02/2015		Soil	BN		Remediation Standards						No starting or evidence of release was observed at this site.				
1311	AOC-115	Storage tank and equipment - Above ground storage area	Direct Showers/Pump	Unetermined	No Sampling Trigger	10/02/2015		Soil	BN		Remediation Standards						Site investigation conducted by the contractor to determine if the above ground storage tank was leaking. No further investigation is planned.				
1321	AOC-116	Other areas of concern - Dislodged area of oil tank	Diesel Powered Emergency Generator	Unetermined	PA	10/02/2015		Soil	BN		Remediation Standards						Site investigation conducted using a short-coupled emergency generator near the Diesel Powered Emergency Generator. They indicate that the emergency generator was operating as it was designed to do. No further investigation is planned.				
1331	AOC-117	Other areas of concern - Dislodged area or tight areas	Diesel Powered Emergency Generator	Unetermined	PA	10/02/2015		Soil	BN		Remediation Standards						Site investigation conducted using a short-coupled emergency generator near the Diesel Powered Emergency Generator. They indicate that the emergency generator was operating as it was designed to do. No further investigation is planned at this time.				